Table 1 **Current Claim** - Tree Details & Recommendations

Tree No.	Species	Ht (m)	Dia (mm)	Crown Spread (m)	Dist. to building (m)	Age Classification	Ownership
T1	Horse Chestnut	6	115	4	4	Younger than Property	Policy Holder
Management history		No significant recent management noted.					
Recommendation		Remove (fell) to near ground level and treat stump to inhibit regrowth.					
T2	Ash	8.5	192	5	4	Younger than Property	Policy Holder
Management history		No significant past management noted.					
Recommendation		Remove (fell) to near ground level and treat stump to inhibit regrowth.					
T3	Cherry	4.75	110 90 Ms	2	2	Younger than Property	Policy Holder
Management history		No significant recent management noted.					
Recommendation		Remove (fell) to near ground level and treat stump to inhibit regrowth.					
T9	Cedar	21.5	650 *	21	23	Similar Age to Property	Policy Holder
Management history		No significant recent management noted.					
Recommendation		No works required at present (subject to review if movement persists).					
TG1	Deodar cedar Atlas cedar	20.5	750 Ms *	16	22	Similar Age to Property	Policy Holder
Management history		No significant recent management noted. Asymmetrical crowns from historical pruning.					
Recommendation		Remove (fell) to near ground level.					

Ms: multi-stemmed * Estimated value