Tax window details 24/80435/COND 22.01.25

Just for clarity, the depth of the tax window cills and headers will sit at the same level as the brick headers and cills for the windows. The brick that forms the tax window will essentially sit where the window sits, and would be set back approx. 30mm into the cavity. Can you let me know if this confirmation is acceptable to discharge part 4 a of the condition?