SU2205096

Monitoring Details:

Level Monitoring

Provider Name: My Home Needs

Instruction Date: 08/09/2023

Reading Date:

Date of Issue: 22/03/2024

Monitoring Interval: Every 8 weeks

Number of Visits: 4

Visits Completed: 4

Visits Outstanding: 0

Client Details:

Client: Crawfords

Job Reference:

Engineer / Handler: -

Monitored Address:

Occupier:

Address: Milldale, South Street, Woodhurst, Huntingdon, Cambridgeshire, PE28


Telephone:

Email:

Front Elevation



Site Plan



SU2205096

Level Readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/09/23	17/11/23	26/01/24	22/03/24				
TBM 1	10.0000	10.0000	10.0000	10.0000				
2	10.0130	10.0131	10.0130	10.0130				
3	10.0284	10.0279	10.0276	10.0274				
4	10.0201	10.0192	10.0179	10.0179				
5	10.0229	10.0233	10.0229	10.0226				
6	9.9943	9.9950	9.9968	9.9968				
7	9.9820	9.9836	9.9861	9.9866				
8	9.9614	9.9615	9.9621	9.9626				
Taken by	N/A	N/A	N/A	SJ				
Serial number				1211525				

Level Movement (Displayed in Millimeters)

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/09/23	17/11/23	26/01/24	22/03/24				
TBM 1	0	0	0	0				
2	0	+0.1	0	0				
3	0	-0.5	-0.8	-1				
4	0	-0.9	-2.2	-2.2				
5	0	+0.4	0	-0.3				
6	0	+0.7	+2.5	+2.5				
7	0	+1.6	+4.1	+4.6				
8	0	+0.1	+0.7	+1.2				

Level Readings - Continuation of levels


	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/09/23	17/11/23	26/01/24	22/03/24				
9	9.9776	9.9765	9.9767	9.9769				
10	9.9783	9.9772	9.9768	9.9769				
Taken by	N/A	N/A	N/A	SJ				
Serial number				1211525				

Level Movement (Displayed in Millimeters) - Continuation of readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	21/09/23	17/11/23	26/01/24	22/03/24				
9	0	-1.1	-0.9	-0.7				
10	0	-1.1	-1.5	-1.4				


SU2205096

Level Readings Chart (Points TBM 1 - 10)



SU2205096

Relative Movement (Relative Survey, for illustration purposes only)



20/09/2023 17/11/2023 26/01/2024 22/03/2024