TREE WORKS APPLICATION - (CON AREA & TPO)

9 BELL LANE

FENSTANTON

HUNTINGDON


PE28 9JX



T1 ASH - FAIR CONDITION, MODERATE DEAD WOOD AND THINNING CROWN

- LIKELY TO BE ASH DIEBACK AS PRESENT ELSEWHERE ON SITE

- EXTENSIVE WALL DAMAGE (SEE REPORT)
- PREVIOUS WALL REPAIRS UNDERTAKE 30 YEAR AGO



REMOVE T1

- REPLACE WITH LIME SPECIES

T2 CHERRY LAUREL

SHADING OUT WOODLAND FLOOR (TREE BELT)

REMOVE TO BENEFIT OTHER SPECIES