Laurel House
26 High Street
Catworth
PE28 0PF

Dear Sir/Madam,

Condition information 15/01146/HHFUL
Condition 3

Please find enclosed revised information relating to the discharge of condition 3 b) and c) - contamination of soils identified during works to Laurel House, 26 High Street Catworth PE28 0PF.

1) Revised Remediation Method Statement

2) Sample location plan & photos

3) Sample results summary

4) Phase 1 Test result report

5) Phase 2 Test result report

I trust this is sufficient to enable discharge of condition 3.

Regards

[redacted]